
 National Transportation Safety Board PRELIMINARY REPORT AVIATION		NTSB ID: ERA09WA076		Most Critical Injury:	
		Occurrence Date: 11/28/2008		Investigated By: Foreign	
		Occurrence Type: Accident			
Location/Time					
Nearest City/Place Anapolis		State	Zip Code	Local Time 1835	Time Zone AST
Aircraft Information					
Registration Number 400SA		Aircraft Manufacturer BEECH		Model/Series Number 58	
Type of Aircraft: Airplane			Amateur Built Aircraft? No		
Injury Summary:		Fatal 4	Serious 2	Minor	None
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On November 28, 2008, at 1835 Atlantic standard time, a Beech 58, N400SA, was destroyed during a local personal flight when it impacted the ground after a low pass at Anapolis JK Airport (SWNS), Anapolis, Goias, Brazil. The pilot and 3 of the 5 passengers were killed, 2 were seriously injured.</p> <p>According to the Aeronautical Accident Prevention and Investigation Center of the Federative Republic of Brazil, the airplane made a low pass over the airport and was observed to enter an aileron roll. The airplane then collided with the ground and exploded.</p> <p>This investigation is under the jurisdiction of the Federative Republic of Brazil. Any further information pertaining to this accident may be obtained from:</p> <p>Research and Investigative Division Aeronautical Accident Prevention and Investigation Center Federative Republic of Brazil SHISQI 05VI COMAR Brasilia-DF Brazil</p> <p>This report is for informational purposes and contains only information released by the Federative Republic of Brazil.</p>					
PRELIMINARY INFORMATION - SUBJECT TO CHANGE					

 National Transportation Safety Board PRELIMINARY REPORT AVIATION		NTSB ID: ERA09WA076			
		Occurrence Date: 11/28/2008			
		Occurrence Type: Accident			
Other Aircraft Involved					
Registration Number		Aircraft Manufacturer		Model/Series Number	
Accident Information					
Aircraft Damage: Destroyed			Accident Occurred During:		
Crew	Name	Certificate No.	Injury		
Pilot	On File				
2					
3					
4					
5					
6					
Operator Information					
Name JH Manutencao De Aeronaves		Operator Designator Code		Doing Business As	
Street Address		City Anapolis		State	Zip Code
-Type of Certificate(s) Held: None					
Air Carrier Operating Certificate(s):					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Non-U.S., Non-Commercial					
Type of Flight Operations Conducted: Personal					
Flight Plan/Itinerary					
Type of Flight Plan Filed: Unknown					
Last Departure Point		State	Airport Identifier		
Same as Accident/Incident Location			SWNS		
Destination		State	Airport Identifier		
Local Flight			SWNS		
Weather Information					
Investigator's Source: Unknown		Facility ID: SBAN		Observation Time (Local): 2100	
Sky/Lowest Cloud Condition:			Ft. AGL		
Lowest Ceiling: Broken		1500 Ft. AGL	Visibility: 6	SM	Altimeter: 29.97 "Hg
PRELIMINARY INFORMATION - SUBJECT TO CHANGE					

National Transportation Safety Board
PRELIMINARY REPORT
AVIATION

NTSB ID: ERA09WA076

Occurrence Date: 11/28/2008

Occurrence Type: Accident

Weather Information

(Continued from page 2)

Temperature:

20 °C

Dew Point:

20 °C

Wind Direction: 80

Wind Speed: 6

Kts.

Gusts:

Kts.

Weather Conditions at Accident Site: Visual Conditions

Administration Data

Notification From

CENIPA, Brazil

Date

FAA District Office/Coordinator

CENIPA

Luis C. Bastos

Investigator-In-Charge (IIC)

Todd G. Gunther